

May 10, 1957

25X1A6a

25X1A9a We received weekly reports from [REDACTED] and Detachments B and C. Jack [REDACTED] at Detachment C reports that all the equipment is functioning smoothly

25X1A6a with many flights and many shots being taken. He has received a spare unit 25X1A9a from the [REDACTED] and is in good shape equipment wise. [REDACTED] B has his five units in good condition and reports that it is very quiet. On May 2 he left to go to Detachment A to check the equipment there in [REDACTED] 25X1A9a absence.

25X1A9a

[REDACTED] vacation is coming to a close and he will leave the ZI on May 11 from Maguire Air Force Base. He is returning directly to his detachment. 25X1A6a 25X1A9a

25X1A9a [REDACTED] the FOG field representative, is now at [REDACTED] with [REDACTED]

[REDACTED] John spent Friday, May 3, at Headquarters in Washington for a briefing and reported to work at [REDACTED] on May 6 25X1A6a

25X1A9a [REDACTED] will spend a week orienting John and will return home to the plant this weekend. Henceforth we will only have 4 field reps, 25X1A9a [REDACTED]

25X1A9a Shipments from the factory during the past week included the lighting box as requested on the telephone April 30 by [REDACTED] Unit No. 51 was shipped 25X1A9a 25X1A6a to the [REDACTED] warehouse B on May 1. Two Mark III handles were shipped to warehouse B and 2 to warehouse A. Each shipment consists of one handle assembly, two adapters, and two cables. On May 7 we completed our shipment of averager assemblies (BA-CR44-32).

Our operating and instruction manuals were printed last week and on May 8 45 were shipped to warehouse A and 74 were shipped to warehouse B as called for in the contracts, respectively.

25X1A9a [REDACTED] and myself attended a suppliers' meeting at Wright Field on May 1. The meeting was with the FOG group only and any small difficulties we had were ironed out. Everything is in good shape and we should close out the contract on June 30 as scheduled, except for the computer which might be a few weeks late.

Jack